

## Release Notes CODESYS Control SL for Weidmüller u-OS

### Compatibility

The CODESYS package can be installed and updated in the CODESYS Development System 3.5.19.7 or later. u-OS 2.2.0 requires the Package Version 4.12.1.0 or later. For instructions on how to migrate from an older u-OS version see the First Steps document. The CODESYS runtime app can be installed and updated on all devices running u-OS 2.1.3 or later. Parametrization of IO-Link devices connected to the UR20-4COM-IO-LINK requires u-OS 2.5.0 or later.

#### **IMPORTANT**

Uninstallation of the app is only possible by doing a factory reset in u-OS. Make sure to backup all user data!

### Version history

The version history below is specific to the CODESYS Control SL for Weidmüller u-OS package and runtime. For general CODESYS Control release notes please refer to [CODESYS Release & Lifecycle \(codesys.com\)](https://www.codesys.com).

#### Package version history

**Version: 4.12.2.0**

**Release Date: December 2025**

#### **Information**

- This package version is compatible with u-remote UR20 Library for CODESYS version 3.0.1 or later.

#### **New supported hardware**

- [2682640000](#) IOT-GW30-4G-NA.

#### **New features**

- Package is now signed by Weidmüller
- Added IO-Link configurator to enable configuration of the UR20-4COM-IO-LINK module and attached IO-Link devices
- CODESYS Control SL for Weidmüller u-OS runtime app can now be managed via the CODESYS Deploy tool. SWU-files for installation via the u-OS Control Center are still available

#### **Bug fixes**

- Added descriptive names for channels of UR20-4DO-PN-2A

#### **Known issues**

- System-Bus Device Manager: Does not show the correct device icon when importing IODD files which are not part of a ZIP-archive. Import the entire archive containing one or multiple IODDs and the icons instead of the individual IODD file
- System-Bus Device Manager: An IO-Link port that is configured with an IODD but whose channel's operation mode is disabled will cause a System bus error
- System-Bus Device Manager: Deploy progress of the IO-Link device configuration is not reported in CODESYS Development System, and the initial deployment can take a few minutes depending on the connected IO-Link devices
- Missing process data description of module UR20-1COM-232-485-422-V2
- Symbolic Access to System bus modules is not possible

**Version: 4.12.1.0**

**Release Date: May 2025**

#### **Information**

- This package version or later is required when using u-OS 2.2.0 or later

- This package version is compatible with u-remote UR20 Library for CoDeSys version 2.2.4 or later

#### New supported hardware

- [2920830000](#) UR20-3EM-400V-AC-CT1A
- [2920840000](#) UR20-3EM-400V-AC-CT5A
- [2920850000](#) UR20-3EM-400V-AC-RC
- [2920860000](#) UR20-3EM-400V-AC-333MV

#### New features

- Updated IO Configurator, required for u-OS 2.2.0 or later
- Updated IoDrvUR20Control library to version 2.0.0.0, required for u-OS 2.2.0 or later
- UR20-4COM-IO-LINK Process Data width has been increased to 32 Byte per channel. No acyclic data and no parametrization of connected IO-link devices

#### Bug fixes

- IoDrvUR20Control: bugfix for running the module diagnosis in the background task IoMgrDiagTask; IO manager cares for consistency in atomic bit access instead of IO driver
- Compile information in Weidmüller library in CODESYS causes warnings about difference between offline and online library

**Version: 4.12.0.0**

**Release Date: September 2024**

#### Information

- This package version or later is compatible with u-OS 2.1.x or earlier
- This package version is compatible with u-remote UR20 Library for CoDeSys version 2.2.3 or earlier

#### New supported hardware

- [1990070000](#) UR20-2AI-SG-24-DIAG
- [1315600000](#) UR20-2PWM-PN-0.5-V2
- [1315610000](#) UR20-2PWM-PN-2A-V2

#### New features

- Support CODESYS Control SL Runtime App Version 4.12.0.0-1
- Updated IoDrvUR20Control library to version 1.0.2.0:
  - System Bus process alarms are supported
  - System Bus diagnosis are supported

#### Bug fixes

- Added modules sometimes do not appear in the device tree
- Malfunction of drag&drop to another CODESYS IDE instance
- Referenced libs are contained in package
- System bus error with 64 modules configured

#### Known issues

- Compile information in Weidmüller library in CODESYS causes warnings about difference between offline and online library.

**Version: 4.7.0.0**

**Release Date: November 2023**

**New supported hardware**

- [2839150000](#) UC20-M3000
- [2839160000](#) UC20-M4000
- [2928020000](#) UC20-WL2000-AC-CAN
- [1315740000](#) UR20-4COM-IO-LINK with limited support. Only Process Data with a fixed width of 16 Byte per channel is supported. No acyclic data and no parametrization of connected IO-link devices

**New features**

- Process Alarms can be enabled as “System Bus” setting
- Diagnostic Alarm can be enabled as “System Bus” setting
- Automatic migration when old project (4.7.0.0) is loaded

**Bug fixes**

- fixes display of UR20-8DIO-P-3W in configuration overview

**Known issues**

- Device serial number, firmware version, hardware version not displayed in online mode

**Runtime version history****Version: 4.12.1.0-1****Release Date: December 2025****Information**

- CODESYS Control SL for Weidmueller u-OS package 4.12.0.0 or later is required to use this runtime version

**New supported hardware**

- [2682640000](#) IOT-GW30-4G-NA

**New features**

- SWU files are signed. u-OS 2.4.0 and later only allows installation of signed SWU files by default.
- The WebVisu fallback page now automatically refreshes every 30s, no manual refresh necessary after initial deployment of a WebVisu or a restart of the CODESYS Runtime

**Bug fixes**

- Optimized memory and storage usage
- RUN LED control has been enhanced to ensure it always reflects the correct runtime status, but may light up slightly later than in version 4.12.0.0-3
- UC20-M3000 & UC20-M4000: RUN LED has been moved from CTRL2 to CTRL1 LED

**Known issues**

- On UC20-WL2000-AC devices, and when combined with UR20-4COM-IO-LINK, a large number of CmpSocketUnix log error messages may appear after a power cycle or runtime restart
- IOT-GW30: Using CANopen can lead to system instability if the physical bus is not terminated on both ends
- A change of the EtherCat I/O task cycle time will be active after a power cycle of the device
- Logfile path cannot be configured. Since logs reside in /tmp/CODESYScontrol.log, this also means that logs cannot be persisted across reboots

**Version: 4.12.0.0-3****Release Date: October 2025**

**Information**

- CODESYS Control SL for Weidmueller u-OS package 4.12.0.0 or later is required to use this runtime version.

**New features**

- Compatibility with u-OS 2.4.0 and later: SWU files are now signed.

**Known issues**

- RUN led only reflects status of CODESYS control SL program after Start/Stop command.
- IOT-GW30: Using CANopen can lead to system instability if the physical bus is not terminated on both ends.
- A change of the EtherCat I/O task cycle time will be active after a power cycle of the device.
- Logfile path cannot be configured. Since logs reside in /tmp/codesyscontrol.log, this also means that logs cannot be persisted across reboots.

**Version: 4.12.0.0-3****Release Date: September 2024****Information**

- CODESYS Control SL for Weidmueller u-OS package 4.12.0.0 or later is required to use this runtime version.

**New features**

- Update CODESYS control version to 4.12.0.0. This version improves license handling. For more information visit CODESYS website: [codesys.com](http://codesys.com).

**Known issues**

- RUN led only reflects status of CODESYS control SL program after Start/Stop command.
- IOT-GW30: Using CANopen can lead to system instability if the physical bus is not terminated on both ends.
- A change of the EtherCat I/O task cycle time will be active after a power cycle of the device.
- Logfile path cannot be configured. Since

**Version: 4.9.0.0-3****Release Date: July 2024****Information**

- CODESYS Control SL for Weidmueller u-OS package 4.7.1.0 or later is required to use this runtime version.

**New features**

- Update installed CODESYS Control SL App on the device.

**Bug fixes**

- UC20-WL2000-AC-CAN: Controller crashes when at least the CANopen Manager is projected.
- UC20-WL2000-AC-CAN: CODESYS Control SL Core 1 utilization goes to 100% when CANopen bus termination is deactivated.
- CODESYS Control SL 4.9.0.0-1 licensing not possible if the PROCON-WEB-ES 6.7 app or higher is installed before the CODESYS Control SL app.
- UC20-WL2000-AC-CAN: Connection cannot be restored after plugging/unplugging the CANopen bus.
- Displays an error during installation due to a missing command.
- App status check causes load peaks.

**Known issues**

- RUN led only reflects status of CODESYS control SL program after Start/Stop command.
- Using CANopen can lead to system instability on IOT-GW30 if the physical bus is not terminated on both ends.
- Multiple errors shown in Installation & Update page that have no effect when updating the app to 4.9.0.0-3.

- A change of the EtherCat I/O task cycle time will be active after a power cycle of the device.

**Version: 4.9.0.0-1**

**Release Date: October 2023**

#### Information

- CODESYS Control SL for Weidmueller u-OS package 4.7.1.0 or later is required to use this runtime version.

#### New supported hardware:

- [2839150000](#) UC20-M3000.
- [2839160000](#) UC20-M4000
- [2928020000](#) UC20-WL2000-AC-CAN

#### New features

- Update CODESYS control version to 4.9.0.0

#### Bug fixes

- App status check shows correct state
- Show hint if CODESYS visualization is not present

#### Known issues

- RUN led only reflects current status of CODESYS control program after Start/Stop command
- Using CANopen can lead to system instability, if the physical bus is not terminated on both ends

**Version: 4.7.0.0-2**

**Release Date: March 2023**

#### Information

- CODESYS Control SL for Weidmueller u-OS package 4.7.1.0 or later is required to use this runtime version.

#### New supported hardware

- [2682620000](#) IOT-GW30
- [2682630000](#) IOT-GW30-4G-EU
- [1334950000](#) UC20-WL2000-AC

#### New features

- Initial release with CODESYS control version 4.7.0.0

#### Known issues

- RUN led only reflects current status of CODESYS control program after Start/Stop command
- Using CANopen can lead to system instability, if the physical bus is not terminated on both ends