Firmware release note of switch series IE-SW-VL08MT

Affected models:

| Device name | Article No. |
|---------------------------|-------------|
| IE-SW-VL08MT-8TX | 1240940000 |
| IE-SW-VL08MT-5TX-1SC-2SCS | 1345240000 |
| IE-SW-VL08MT-6TX-2SC | 1344770000 |
| IE-SW-VL08MT-6TX-2ST | 1240990000 |
| IE-SW-VL08MT-6TX-2SCS | 1241020000 |

Version 3.5.36 Released: May 2025

Bug Fixes:

- Fixed [CVE-2025-41649]: Out-of-bounds write vulnerability. This vulnerability is caused by insufficient input validation, which allows writing data beyond buffer boundaries.
- Fixed [CVE-2025-41650]: Denial-of-Service vulnerability. This vulnerability allows attackers to exploit a service, originally designed for deployment purposes.
- Fixed [CVE-2025-41651]. Missing authentication vulnerability. This vulnerability allows attackers to manipulate device configurations without requiring authentication.
- Fixed [CVE-2025-41652]: Frontend authorization logic disclosure vulnerability. Exploitation of this vulnerability could allow attackers to bypass authentication, perform brute-force or MD5 collision attacks, and gain unauthorized access to sensitive configurations or disrupt services.
- Fixed [CVE-2025-41653]: A specially crafted HTTP message header can lead to denial of service.

Version 3.5.34 Released: February 2025

Bug Fixes:

- Fixed [CVE-2016-2183]: Weak SSL/TLS Key Exchange.
- SNMPv3 encryption key no longer visible when entering via web-interface.

Version 3.5.32 Released: June 2024

Improvements:

- Update OpenSSL 1.0.2k to support TLS v1.2 for accessing switch's web interface via https with current internet browsers.
- Complete serial number (12-digits) will be shown in the web interface now (applicable only from Hardware Revision V 1.4.2).

Bug Fixes:

• Fixed the issue of "Set device IP" function sometimes does not answer DHCP Discovery messages sent from a DHCP client, resulting in the client not being able to obtain an IP address.

Version 3.5.22 Released: November 2019

Improvements:

- Switch's web interface can now be accessed encrypted via https
- · Added new Search Service protocol (encrypted) to be used with new "Weidmüller Switch Configuration Utility"
- Added Management Interface page to enable/disable Search Service (unencrypted) and Search Service (encrypted) in Main Menu > Basic Settings > Security > Management Interface
- Switch can be addressed via Modbus requests using TCP and UDP protocol

Version 3.5.2 Released: September 2016

Improvements:

- Pass the ODVA certification of industrial protocol "EtherNet/IP"
- Pass the PI certification of industrial protocol "PROFINET RT"
- · Add some minor SNMP OIDs
- · Enhancement of multicast performance
- · Elimination of some vulnerability issues
 - > Web interface: Ping function in diagnostic menu vulnerable to XSS attack
 - > Switch may reboot when using special URL to attack the web user interface.
 - ➤ User account privileges could be changed by web developer plug-in of Firefox browser.

Bug Fixes:

- Improvement of stability of PROFINET I/O communication
- Configuration import failed if system name was too long
- RSTP function was incompatible with some 3rd party devices
- Wrong counter information of switch packets when displayed in Web interface or when read via SNMP
- Wrong message "Login Authentication failed" has been stored in the log file though login procedure was successful

Version 3.3.26 Released: February 2016

Improvements:

PROFINET protocol automatically activated in factory default settings

Bug Fixes:

• Web interface displayed errors under Java 8 environment when opening the monitoring menu (due to new Java security enhancements implemented in version 8).

Version 3.3.16 Released: April 2014

Improvements:

- Support of RSTP-2004
- Support of Hybrid VLAN
- · Configuration of limitation of Egress rates
- · Unknown unicast filtering
- CPU loading monitoring
- Change IP without reboot
- DHCP Discover retry configuration
- GARP timer adjustment
- Loop-protection
- Link Fault Shutdown (Disable mode in "Rate Limit" function)
- · Implementation of industrial protocol "EtherNet/IP"
- · Implementation of industrial protocol "PROFINET RT"

Bug Fixes:

Switch reboots when receiving IGMP v3 packets (commonly used in Windows 7)

Version 2.7.30 Released: August 2013

Improvements:

- Function IGMP snooping added
- Function IEEE 802.1Q VLAN added

Version 2.7.24 Released: April 2011

First release