

## Technical change to HDC RockStar® ModuPlug MBUS 2

Dear Madam or Sir,


The below listed articles will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications are performed for reasons of product improvements.

### 1. Initial situation

Possibility of a conductive connection between ModuPlug frame and shield contact.

### 2. Technical change

- Geometrical optimization of the contact carrier to accommodate a metal clip.
- Printing optimized. Raised lettering replaced by laser printing.



### 3. Reason for change

- Product improvement
- Possibility to accommodate a metal clip

### 4. Availability

Q2 / 2020

### 5. Affected parts

1428990000	HDC MBUS 2 MC
1429020000	HDC MBUS 2 FC

### 6. Data

PCN-number:	PCN-PB72-20200131-00-A
Date of publishing:	2020, January 31
Duration of validity:	Until further notice
Revision number:	00-A

We are very sorry for any inconveniences caused and are doing everything possible to implement this product change as smoothly as possible, without any big influences on delivery times and general functions.

For further questions please contact your sales office directly. All contacts for sales representatives are available here: [www.weidmueller.com/contact](http://www.weidmueller.com/contact)

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG  
Klingenbergstraße 26, 32758 Detmold, Germany

**Weidmüller** – Your partner in Industrial Connectivity  
We look forward to sharing ideas with you – **Let's connect.**