



Page 1

Product consolidation RIDERSERIES RCI relays

Dear Madam or Sir,

we hereby inform you that the below listed articles change. Please pass this product information only to your employees and possibly to your customers

1.	General Overview			
	Type of notification:	⊠ PCN	☐ PDN	⊠ Short-term action (<6 months)
	Short-term action due t	<u>o:</u>		
	Software / Firmware I	Bugfix		☐ Short term delivery stop by supplier
	☐ Short term recall by s	supplier		Force majeure
	Product improvement	t with customer bene	efit	⊠ other
2.	General Information			
cor All	nsolidations.			curity require temporary product adjustments or even g commitment to continuous improvement and ongoing
3.	Availabillity			

Deliveries in which the previous and new variants are mixed, unfortunately we cannot avoid.



4. Product comparison

The following adjustments were made to the products:

- Changeover of printing from pad printing to laser printing
- Color coding of the coil voltage:
 - o Is removed for the variants without test button
 - o Is done via the color of the test button for the variants with test button (AC: red / DC: blue)

The adjustment has no effect on the performance or technical data of the products. It is a visual adjustment only.

Versions without test button:

Before:



New:



Versions with test button:

Before:



New:






5. Affected parts

The following products are affected by this change:

Type code	Part-No.
RCI314012	8869800000
RCI314024	8869810000
RCI314048	8869820000
RCI314110	8869830000
RCI314524	8869840000
RCI314615	8869850000
RCI314730	8869860000
RCI374012	8869950000
RCI374024	8869960000
RCI374524	8869990000
RCI374730	8870010000
RCI314AB2	8870090000
RCI314AC4	8870100000
RCI314AE8	8870110000
RCI314BB0	8870120000
RCI314R24	8870130000
RCI314S15	8870140000
RCI314T30	8870150000
RCI374AB2	8870240000
RCI374AC4	8870250000
RCI374AE8	8870260000
RCI374BB0	8870270000
RCI374R24	8870280000
RCI374S15	8870290000
RCI374T30	8870300000

Toma anda	David Na
Type code	Part-No.
RCI424AB2	8870170000
RCI424AC4	8870180000
RCI424AE8	8870190000
RCI424BB0	8870200000
RCI424R24	8870210000
RCI424S15	8870220000
RCI424T30	8870230000
RCI484AB2	8870310000
RCI484AC4	8870320000
RCI484AE8	8870330000
RCI484BB0	8870340000
RCI484R24	8870350000
RCI484S15	8870360000
RCI484T30	8870370000
RCI424012	8869870000
RCI424024	8869890000
RCI424048	8869900000
RCI424110	8869910000
RCI424524	8869920000
RCI424615	8869930000
RCI424730	8869940000
RCI484012	8870020000
RCI484024	8870030000
RCI484048	8870040000
RCI484110	8870050000
RCI484524	8870060000
RCI484615	8870070000
RCI484730	8870080000





Page 4

We are very sorry for all the inconveniences caused and doing everything to adjust this product change as smooth as possible without big influence on delivery times and general functions.

For further questions please contact your sales office directly. All contacts for sales representatives are available here: http://www.weidmueller.com/contact

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG Klingenbergstraße 16, 32758 Detmold, Germany Weidmueller – Your partner in Industrial Connectivity We look forward to sharing ideas with you – Let's connect.